Page 1 of <u>7</u>



# TENNESSEE DEPARTMENT OF TRANSPORTATION **EROSION PREVENTION/SEDIMENT CONTROL**

**INSPECTION REPORT** 

Reason For Inspection:

1st Weekly

2nd Weekly

2.24.12 DATE:

State Route (SR) / US Route or Road Name and Description:							Are correct	ive actions	required by	this inspec	ction report (Y/N):	
Wolf River Blvd.						NO						
County(ies): TDOT PIN: NPDES Permit (NOC)			#:	Number of	New	Number of	Recurring	Number of New	Number of Un-Corrected			
SI	nelby	1016	15	-	TNR153299	9	Corrective	Actions:	Corrective	Actions:	Sediment Releases:	Sediment Releases:
TDOT Cons	truction No.:	TDOT Contra	ict No :	Contractor:	4.00		_					
	1535-54	1301 0011110	.00110		Enterprise	s Inc.						2
prepared und designed to a information p manage the	er penalty of law der my direction assure that quali resented. Base system, or those	or supervision i fied personnel p d on my inquiry persons directl	n accordanc properly gath of the perso ly responsibl	e with a systenered and evant on or persons on for gathering	em aluated who ng the			ld "Jerry" S	tanfill	9	Signature:  Signature:	Starfer
information, I cerify that inspections of storm water discharge points (outfalls) and of erosion and sediment controls have been performed as recorded in the table above. I certify that erosion and sediment controls in the drainage area of the identified outfall where installed as planned and designed in working order as				the table a of the		Contractor EPSC Inspectors:  Tom Acuff and/or Steve Ballard  Signature:				Jam /	lough	
recorded in the	he table above. I	I am aware that	there are si	gnificant pena	allies for	COG EPS	C Project M	anager:			Signature:	00
submitting fa knowing viola	lse information, i ations.	including the po	ssibility of fi	ne and impre	sonment for	Timothy Bierdz						
		TDOT EPSO	C Inspectio	n Weekly R	Rainfall Dat	a Log					/ /	
		Predicted	Rainfall	Rainfall	Rainfall	Rainfall	Rainfall	Rainfall			ntractor Agrees with Ir	spection Report:
Date	Day of Week			Gauge 2	Gauge 3	Gauge 4	Gauge 5	Gauge 6	Duration	NO	or YES	
	Sunday	(%)	(in)	(in)	(in) N/A	(in) N/A	(in) N/A	(in) N/A	(hr)	іт ічо, ехрі	ain and initial:	
2 27 10	Monday	/ 5			N/A	N/A N/A	N/A	N/A				M
2.27.12	Tuesday	/0	0.40	0.40	N/A	N/A	N/A	N/A	8.5			
2. 22.12	Wednesday	30	0.70	0.70	N/A	N/A	N/A	N/A	0, 3			
2.23.12	Thursday	40	0.55	0.70	N/A	N/A	N/A	N/A	1.5			
2.24.12	Friday	10	(),00	0.70	N/A	N/A	N/A	N/A	1.0			
2. 25.12	Saturday	0			N/A	N/A	N/A	N/A			1000	
2.26.12	Sunday	0	10.05 20 00.24		N/A	N/A	N/A	N/A			1	
	Monday				N/A	N/A	N/A	N/A				1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
10012-1011-102-15										(Add	ditional pages may be	attached, if needed)
		Predicted Pre	ecipitation S	Source:		www.wea	ather.com					Page 1 of <b>7</b>

	ÖF	THE	57	<b>.</b>
18	ā	XX	TURI	
	AGR	CU	TURE 7	1
1	<u>\</u>	7мі 1796		1

State/US Route or Road Name:	Wolf River Blvd.

TO	OT	0-	1	ection	- 41-

TOOF 4	-3537-54	

TDOT Contract No.:		
--------------------	--	--

**CONDITION CODES** 

Date	2/24/2012

Outfall Name or Station No.	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stabilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
11	1	14+14	LT	2/24/2012		22,35	FM	Monitoring outfall.
1A	1	21+50	RT	2/24/2012		41	FM	Const. of RCBC Pedestrian Underpass in progress. Construction activity during inspection.
1B	1	22+00	RT	2/24/2012		12,21,35	s	Temp. stable.
1C	1	21+00	LT	11/7/2011	T = 10-6-11	12,15,33,35	S	Temp. stable.
2A	1	33+50	LT,CL	1/20/2012		12,15,16	S	Temp. stable.
2B	1	35+50	LT	2/24/2012		16,24	FM	Weekly cleaning for stream crossing required, until further notice.
3	1	34+50	LT	10/27/2011		16	FM	Outfall slopes north of temp. stream crossing are showing signs of failure.
4	1	40+00	RT	12/12/2011	T = 10-24-11	15,16,43	S	Temp. stable.
5A	1	49+00	RT	2/24/2012		16,33	FM	Continue construction of proposed RCBC.
5B	1	50+00	RT	2/24/2012		9,16,33	FM	Continue construction of proposed RCBC.

## **EROSION AND SEDIMENT CONTROL MEASURE CODES**

1	Temporary Silt Fence / Filter Barrier	15	Temporary seeding with Mulch	29	Excess Dirt Removed from Rdwy. Daily	M	Maintenance
2	Temporary Diversion Berm or Ditch	16	Temporary Mulch	30	Haul Roads Dampened for Dust Control	U	Upgrade Needed (Failure Noted)
3	Temporary Slope Drain	17	Erosion Control Blanket	31	Ditch Liner	R	Replacement Needed
4	Rock Check Dams	18	Flexible Channel Liner	32	Rock Silt Screen	FM	Future Maintenance
5	Brush Barrier	19	Catch Basin / Storm Inlet Protection	33	Temporary Silt Fence with Backing	С	Cleaning Needed
6	Sediment Removal	20	Riprap Outlet Structure	34	Enhanced Silt Fence	1	Increase Measures
7	Straw Bale Check	21	Riprap Energy / Velocity Dissipater	35	Sediment Tube	w	Too Wet to Work Conditions
8	Sand Bags	22	Curb, Gutter, or Storm Sewer Protection	36	Sediment Dam	RO	Repeat Occurrence
9	Sediment Trap / Basin	23	Temporary at Construction Exit / Entrance	37	Concrete Washout, other pollution Issues	SR	Sediment Release
10	Temp Sediment Filter Bag / Dewatering	24	Temporary Stream Crossing	38	Berm (soil, riprap, rock)	FS	Final Stabilized
11	Polyethylene Sheeting	25	Turbidity Barrier / Silt Boom	39	Gabion	S	Stable (No Action Needed)
12	Machined Rip Rap	26	Temporary Stream Diversion	40	Sheet Pilling	CM	Corrections currently being made
13	Geotextile	27	Preserve Natural Resource / Buffer Zone	41	Haul Road	Other (O31):	
14	Permanent Seeding with Mulch or Sod	28	Mineral Aggregate Base on Subgrade	42	Bridge Construction	Other (O#2):	
				43	Stream Realignment	Other (O#3):	

State/HS	Route or Road Name:	W

Nolf River Blvd.

DOT	Construction No.:	79954-3537	-5

TDOT Contract No.:	
--------------------	--

Date 2/24/2012

Outfall Name or Station No.	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stabilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
5C	1	44+00	LT	2/24/2012		16,24,33	FM	Weekly cleaning for stream crossing required.
6	1	56+00	LT	2/24/2012			FM	Activity around and in pond during inspection.  Monitoring BMP's
7	1	60+00	RT	10/24/2011		16, 33	s	Temp. stable.
8A	1	73+00	RT	2/24/2012		16,24,42	FM	Weekly cleaning for stream crossing will be required, until further notice.
8B	2	75+50	RT	2/24/2012		4,16,35,41	FM	Monitoring temp. BMP's.
8C	1	71+00	LT	2/21/2012	P = 2-21-12 riprap installed at Bridge 2, East Bank	16,35,42	S	Bridge 2, Abutment 1 rip rap installed along bank slopes.
8D	2	75+50	LT	2/9/2012	P = 2-2-12 riprap installed at Bridge 2, East Bank	12,16,35,42	FM	Monitoring temp. BMP's north of rip rap in place at bridge 2 east bank.
8E	1	71+50	LT, RT or CL	2/24/2012		12,42	FM	Rip Rap installed under Bridge as per plans.
9A	2	80+00	RT	9/29/2011	T = 10-3-11	6,15,33,35	S	Temp. stable.
9B	2	80+00	LT	9/29/2011	T = 10-3-11	15,16,17,,35	S	Temp. stable.

## **EROSION AND SEDIMENT CONTROL MEASURE CODES**

## **CONDITION CODES**

1	Temporary Silt Fence / Filter Barrier	15	Temporary Seeding with Mulch	29	Excess Dirt Removed from Rdwy. Daily	M	Maintenance
2	Temporary Diversion Berm or Ditch	16	Temporary Mulch	30	Haul Roads Dampened for Dust Contro	l U	Upgrade Needed (Failure Noted)
3	Temporary Slope Drain	17	Erosion Control Blanket	31	Ditch Liner	R	Replacement Needed
4	Rock Check Dams	18	Flexible Channel Liner	32	Rock Silt Screen	FM	Future Maintenance
5	Brush Barrier	19	Catch Basin / Storm Inlet Protection	33	Temporary Silt Fence with Backing	С	Cleaning Needed
6	Sediment Removal	20	Riprap Outlet Structure	34	Enhanced Silt Fence	1	Increase Measures
7	Straw Bale Check	21	Riprap Energy / Velocity Dissipater	35	Sediment Tube	W	Too Wet to Work Conditions
8	Sand Bags	22	Curb, Gutter, or Storm Sewer Protection	36	Sediment Dam	RO	Repeat Occurrence
9	Sediment Trap / Basin	23	Temporary at Construction Exit / Entrance	37	Concrete Washout, other pollution Issue	es SR	Sediment Release
10	Temp Sediment Filter Bag / Dewatering	24	Temporary Stream Crossing	38	Berm (soil, riprap, rock)	FS	Final Stabilized
11	Polyethylene Sheeting	25	Turbidity Barrier / Silt Boom	39	Gabion	S	Stable (No Action Needed)
12	Machined Rip Rap	26	Temporary Stream Diversion	40	Sheet Pilling	CM	Corrections currently being made
13	Geotextile	27	Preserve Natural Resource / Buffer Zone	41	Haul Road	Other (O31):	
14	Permanent Seeding with Mulch or Sod	28	Mineral Aggregate Base on Subgrade	42		Other (O#2):	

State/US Route or Road Name	State/US	Route	or Road	Name:
-----------------------------	----------	-------	---------	-------

Wolf River Blvd.

TDOT Construction No.: 79954-3537-54

TDOT	Contract No.:	

_		THE	37	
1	Z	XX	A	<i>.</i>
	AGR	cu	CURE 7	M
10	10	ME		<i>"</i>
565	_	796	بببب	

2/24/2012 Date

Outfall Name or Station No.	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stabilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
9C	2	79+50	LT	9/29/2011	T = 10-03-11	15,16,20,33	S	Temp. stable.
10A	2	85+00	RT	2/24/2012		15,16,35,41	СМ	Corrections being made during inspection.
10B	2	85+00	RT	2/24/2012		15,16,35,41	СМ	Corrections being made during inspection.
10C	2	85+50	LT	11/14/2011		15,16,35,41	S	Temp. stable.
10D	2	84+50	LT	1/6/2012		15,16,35,41	FM	Monitoring temp. BMP's.
11A	2	92+50	RT	2/24/2012		35,41	СМ	Corrections being made during inspection.
11B	2	92+50	LT	1/6/2012	T = 01-10-12	10,32,35,41	S	Monitoring temp. BMP's.
11C	2	92+00	LT	1/6/2012	T = 01-10-12	10,32,35,41	S	Monitoring temp, BMP's.
	1	11+28	LT	2/24/2012		19,35	FM	Daily cleaning is required, until further notice.
	1	13+40	RT	2/24/2012		23,29,30	FM	Daily cleaning will be required, until further notice.
	1	107+75	CL	2/24/2012	TEACURE CORE	23,29,30	FM	Daily cleaning will be required, until further notice.

### **EROSION AND SEDIMENT CONTROL MEASURE CODES**

#### Temporary Silt Fence / Filter Barrier 15 Temporary Seeding with Mulch Temporary Diversion Berm or Ditch 16 Temporary Mulch Temporary Slope Drain Erosion Control Blanket 17 4 Rock Check Dams 18 Flexible Channel Liner 5 Brush Barrier 19 6 Sediment Removal 20 Riprap Outlet Structure Straw Bale Check 21 8 Sand Bags 22

- Temp Sediment Filter Bag / Dewatering 10 11 Polyethylene Sheeting
- 12 Machined Rip Rap 13 Geotextile

Sediment Trap / Basin

14 Permanent Seeding with Mulch or Sod

- Catch Basin / Storm Inlet Protection
- Riprap Energy / Velocity Dissipater
- Curb, Gutter, or Storm Sewer Protection 23 Temporary at Construction Exit / Entrance
- 24 Temporary Stream Crossing Turbidity Barrier / Silt Boom
- 26 Temporary Stream Diversion 27 Preserve Natural Resource / Buffer Zone Mineral Aggregate Base on Subgrade

- Excess Dirt Removed from Rdwy. Daily
- 30 Haul Roads Dampened for Dust Control 31 Ditch Liner
- 32 Rock Silt Screen
- 33 Temporary Silt Fence with Backing
- Enhanced Silt Fence 34 35 Sediment Tube
- 36 Sediment Dam
- 37 Concrete Washout, other pollution Issues
- 38 Berm (soil, riprap, rock)
- 39 Gabion 40 Sheet Pilling
- Haul Road

40	D-1	C
42	Bridge	Construction

## **CONDITION CODES**

- Maintenance
- Upgrade Needed (Failure Noted)
- Replacement Needed
- FM Future Maintenance Cleaning Needed
- Increase Measures
- W Too Wet to Work Conditions
- Repeat Occurrence SR Sediment Release
- FS Final Stabilized

Other (O#3):

S Stable (No Action Needed) Corrections currently being made

Other (O31):	 **	
Other (O#2):		

7

9

State/US	Route o	r Road	Name:

Wolf River Blvd.

TDOT	Cone	truct	ion	No
1001	COUR	แนะเ	1101	INO.

79954-3537-54

Date	2/24/2012	
	LILTILUIL	

			***************************************		Date of	Existing		
Outfall Name	Rain	Approx.	LT, RT or	Date Last	Stabilization	EPSC	Current	
or Station No.	Gage	Station No.	Centerline	Disturbed	and Code	Control	Condition	Corrective Action(s) or Comments
*(Existing	No.	From / To			T = Temp.	Measure	Codes*	
Structure)					P = Perm.	Codes*		
								Daily cleaning will be required, until further
* 109+51	2	East side of WRB	RT	2/24/2012		19,22	FM	notice.
2008 No. W. March 1957 25 195		South side of	ette Ovak sen					Daily cleaning will be required, until further
* 109+11	2	Farmington	RT	2/24/2012		19,22	FM	notice.
		North side of	200-40	SECRETARIO CONTRACTOR DE ATTORA	The state of the s	W000 ET 10		Daily cleaning will be required, until further
* 12+80	_ 1	WRB	LT	2/24/2012		19,22	FM	notice.
		Walking Trail						
	1	36+00	LT	7/20/2011	T = 7-20-11	5,35	S	Temp. stable.
	4	Ct- 20, 50 Ol-	1.7	7/00/0044	T 00444	40		
<del>1                                      </del>	1	Sta. 29+50 Slope	LT	7/20/2011	T= 9-01-11	16	S	Temp. stable.
		Sta. 13+40 -						Haul roads dampened frequently for dust
	1 & 2	Sta. 107+75	LT, RT or CL	2/24/2012		3,30,38	FM	control, until further notice.
		70.50 400.40		0.0000044			_	
W. Marie	2	76+50 - 103+46	RT	9/29/2011	T = 10-03-11	3,15,16,35,38	S	Temp. stable.
-0.00 907 9	2	92+50 - 107+00	LT	9/29/2011	T = 10-03-11	3,15,16,35,38	S	Temp. stable.
								Daily cleaning will be required, until further
	1	6+75	LT	2/24/2012		19,22	FM	notice.
	1	27+00	RT	10/3/2011	T= 10-03-11	15,16	S	Temp. stable.
	1	34+00	RT	8/25/2011	T= 8-25-11	16	S	Temp. stable.
		EROSI	ON AND SEDIMEN	T CONTROL ME	ASURE CODES		1000	CONDITION CODES

## **EROSION AND SEDIMENT CONTROL MEASURE CODES**

1	Temporary Silt Fence / Filter Barrier	15	Temporary Seeding with Mulch	29	Excess Dirt Removed from Rdwy. Daily	М	Maintenance
2	Temporary Diversion Berm or Ditch	16	Temporary Mulch	30	Haul Roads Dampened for Dust Control	U	Upgrade Needed (Failure Noted)
3	Temporary Slope Drain	17	Erosion Control Blanket	31	Ditch Liner	R	Replacement Needed
4	Rock Check Dams	18	Flexible Channel Liner	32	Rock Silt Screen	FM	Future Maintenance
5	Brush Barrier	19	Catch Basin / Storm Inlet Protection	33	Temporary Silt Fence with Backing	С	Cleaning Needed
6	Sediment Removal	20	Riprap Outlet Structure	34	Enhanced Silt Fence	Î	Increase Measures
7	Straw Bale Check	21	Riprap Energy / Velocity Dissipater	35	Sediment Tube	W	Too Wet to Work Conditions
8	Sand Bags	22	Curb, Gutter, or Storm Sewer Protection	36	Sediment Dam	RO	Repeat Occurrence
9	Sediment Trap / Basin	23	Temporary at Construction Exit / Entrance	37	Concrete Washout, other pollution Issues	SR	Sediment Release
10	Temp Sediment Filter Bag / Dewatering	24	Temporary Stream Crossing	38	Berm (soil, riprap, rock)	FS	Final Stabilized
11	Polyethylene Sheeting	25	Turbidity Barrier / Silt Boom	39	Gabion	S	Stable (No Action Needed)
12	Machined Rip Rap	26	Temporary Stream Diversion	40	Sheet Pilling	Other (O31):	10)
13	Geotextile	27	Preserve Natural Resource / Buffer Zone	41	Haul Road	Other (O#2):	
14	Permanent Seeding with Mulch or Sod	28	Mineral Aggregate Base on Subgrade	42	Bridge Construction	Other (O#3):	

THE ST
APA
1796

State/US Route or Road Name:	Wolf River Blvd

TDOT Construction No.:

79954-3537-54

TDOT Contract No.:

CONDITION CODES

Other (O#3):

Date

**EROSION AND SEDIMENT CONTROL MEASURE CODES** 

Mineral Aggregate Base on Sub grade

2/24/2012

*******	2							
Outfall Name or Station No.	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stabilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
	1	21+33 - 26+00	LT	2/2/2011	T = 10-6-11	3,15,16,33,35,3 8,41	S	Temp. stable.
	1	21+33 - 26+00	RT	10/10/2011	T = 10-6-11	3,15,16,33,35,3 8,41	S	Temp. stable.
	1	25+00	LT	12/14/2011	T = 10-6-11	15,16,33,35,41	S	Temp. stable.
	1	25+00	RT	9/29/2011	T = 10-6-11	15,16,33,35,41	S	Temp. stable.
	1	27+50	RT	10/6/2011	T = 10-6-11	15,16,33,35,41	S	Temp. stable.
	1	31+90	RT	9/29/2011	T = 10-6-11	15,16,35	S	Temp. stable.
	1	15+60 North side of	LT & RT	1/23/2012		15,16,33,35	FM	Headwalls are in place. Clean up and stabilize disturbed areas. No activity during visit.
* 108+37	2	WRB	ĻТ	2/24/2012		19,22	FM	Daily cleaning will be required, until further notice.
	1	23+00 - 26+00	RT	9/29/2011	T = 10-6-11	33,41	s	Temp. stable.
	1	25+00	RT	2/13/2012		15,33,35	FM	Remove sediment around existing trees in existing wetland. See photo

#### Temporary Silt Fence / Filter Barrier Temporary Seeding with Mulch 29 Excess Dirt Removed from Rdwy. Daily M Maintenance Temporary Diversion Berm or Ditch 2 16 Temporary Mulch 30 Haul Roads Dampened for Dust Control U Upgrade Needed (Failure Noted) 3 Temporary Slope Drain 17 Erosion Control Blankel 31 Ditch Liner Replacement Needed Rock Check Dams Flexible Channel Liner 32 Rock Silt Screen FM Future Maintenance 5 Brush Barrier 19 Catch Basin / Storm Inlet Protection Temporary Silt Fence with Backing C Cleaning Needed 6 Sediment Removal 20 Riprap Outlet Structure Enhanced Silt Fence 1 Increase Measures Straw Bale Check 7 21 Riprap Energy / Velocity Dissipater 35 Sediment Tube W Too Wet to Work Conditions Sand Bags 8 Curb, Gutter, or Storm Sewer Protection 36 Sediment Dam RO Repeat Occurrence 9 Sediment Trap / Basin Temporary at Construction Exit / Entrance Concrete Washout, other pollution Issues SR Sediment Release 10 Temp Sediment Filter Bag / Dewatering 24 Temporary Stream Crossing 38 Berm (soil, riprap, rock) FS Final Stabilized Polyethylene Sheeting 11 25 Turbidity Barrier / Silt Boom 39 Gabion S Stable (No Action Needed) Machined Rip Rap 12 26 Temporary Stream Diversion Sheet Pilling Other (O31): 13 Geotextile Preserve Natural Resource / Buffer Zone Haul Road 41 Other (O#2):

**Bridge Construction** 

Permanent Seeding with Mulch or Sod



